



CAUTION: PROTECT BALLS AND RACES FROM SAWDUST, DIRT, PAINT, ETC. SHOULD BEARING BECOME "ROUGH" FROM DIRTY RACES, FLUSH THOROUGHLY WITH HOT SOAPY WATER, RINSE, OVEN DRY AND RE-OIL.



THERE MAY BE 2 TO 4 BALLS LEFT OUT DUE TO MANUFACTURING PROCESS.

PART STAMPED WITH TRIANGLE NAME STAMP

| 3 | BALLS12 | BALL | 1 |
|-------------------------------|-------------|--------------|-----|
| 2 | 1866 | PLAIN RACE | 1 |
| 1 | 1865 | LOCKING RACE | 1 |
| DET | PART NUMBER | DESCRIPTION | AMT |
| C TRIANGLE MANUFACTURING CO. | | | |
| NAME 12" LAZY SUSAN BRG. ASSY | | | |
| FIT | | USED IN | |
| ELECTRO GALV | | //// | |
| DATE 7-14-76 | | PART NO. | |
| DRAWN LML | | 12C | |
| CHECKED SP | | | |
| SCALE 1 / 1 | | | |

CHANGE LEVEL
P 07-31-06